

Recent Notice to Anson Madison Water District Customers:

EPA recently changed how lead water lines in water systems are regulated, as such, the District was required to examine all of the water service lines in the system. AMWD examined over 2000 water services (the pipe that runs from the District's mains in the street to and into the customer's residence or business). Here is a short video that offers additional information on lead service line inventories.
<http://www.cityoflancafterpa.gov/lead-service-line/>.

Of these water services, AMWD found 0 lead lines and that is very good news! We found 0 that were galvanized iron, and that too is good news!

Next Steps for the District: We had 1192 water services that were "unknown" as a result of lack of records, lack of construction information, no visual inspection. If you received this notice, we need to set up an appointment for inspection or you may text a picture of the water service line to 207-530-4873. This picture should include the water service line where it enters the residence or business from the floor (or wall). Please be sure to focus the camera on the material of the pipe. Also include your name and the location of the water service line.

AMWD is in compliance with this new US EPA mandate and we will continue to work with the customers to secure the information needed from those yet to be inspected.



DRINKING WATER NOTICE

Anson and Madison Water District

PWSID # ME00909300

Our Public Water System Has Completed an Initial Service Line Inventory

We have found/identified Lead Service Lines, Galvanized Service Lines Requiring Replacement (GRR) or Unknown Service Lines (where we do not know what the line material is).

During the initial service line inventory that was completed on October 16th 2024, Anson and Madison Water District has classified the service line supplying water to your address as either lead, galvanized requiring replacement (GRR), or as a lead status unknown service line (material of line not known).

WHAT WAS FOUND:

Your Service Line Material Classification Definitions:

Definitions of Classification

- **Lead-** A portion of pipe that is made of lead, which connects the water main to the building inlet.
- **Galvanized Requiring Replacement-**Galvanized steel service line that is or was at any time downstream of a lead service line or is currently downstream of a "Lead Status Unknown" service line.
- **Lead Status Unknown-** Service line material is not known to be lead, galvanized requiring replacement, or a non-lead service line, such as where there is no documented evidence supporting material classification.
- **Non-Lead-** Service line material is determined through an evidence-based record, method, or technique not to be lead or galvanized requiring replacement.

HOW THIS WAS DETERMINED:

Verification Method Used to Determine Service Line Material:

- Field Inspection by PWS
- Records Review
- Customer Self-Identification

Location: Weston Ave, Madison, Maine 04958

System Owned Portion	Customer Owned Portion	Classification
Unknown - Unlikely Lead	Unknown - Unlikely Lead	Unknown

What we classified the service

